


## TRAY ASSEMBY PARTS SPeVAP<sup>®</sup> Multi-Function Solvent Evaporator

- A Tray Top
- B Rubber Gasket
- C Gasket Brace
- D Tray Sides
- E Tray Tube Guide (Middle Row)
- F Tray Bottom








## **TRAY ASSEMBLY AND ADJUSTMENT**

Take the gasket (B) for the desired vial size and lay on top of the gasket brace (C). Make sure to line up the small thru holes in the gasket with the threaded holes in the gasket brace. Take the sheet metal tray top (A) and set on top of the gasket and gasket brace.

Use the eight tray top screws and secure all three pieces together. (Fig. 1) Placement of tray gasket on tray brace (Left) and placement of tray top on gasket/brace. (Top)

## 1

## TRAY ASSEMBLY AND ADJUSTMENT Continued



(Fig. 2) Tray sides attached to top tray assembly.




Caution: Alignment of tray guide with tray top is crucial to avoid less then optimal drying conditions (ie: skewed tube placement)



Install the tray tube guide (E) - to act as the tube guide. The guide is attached in the same manner as the tray top. Vertical placement will vary based on vial size.

(Fig. 3) Tray guide attachment to assembly of tray sides and top

**NOTE:** If using autosampler vials, omit the middle rack (E) in tray assembly. Attach the rack bottom (F) underneath the tray top (A) affixed with appropriate gasket. (12-13mm / autosampler vial gasket)



2